



SILT FENCE NOTES:

1. Attach fabric to mesh top and bottom @ 24" o.c. using approved metal devices.
2. Attach mesh to posts with approved metal devices @ 12" o.c.
3. Fabric top shall be 26" min. above ground



NOTES:

1. Place straw bales as directed by the engineer to slow and control runoff on slopes and in swales and gullies. Do not use to replace required silt fencing.
2. Siltation and detention controls shall be maintained for one year after construction is complete and permanent erosion control measures are operational.
3. Hydroseeding may replace seeding and straw mulching. Use seed, wood fiber or split straw mulch, and starting fertilizer. Tack with PAM or Guar. Plantago tackifier is not approved. Apply 2000 lbs/acre, minimum, except apply 2500 lbs/acre on slopes steeper than 3 to 1.

06 dwc

EROSION BARRIERS

PAGE NO:

29